MAP FINDINGS Map ID

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

33 **BELLWOOD QUARRY US BROWNFIELDS** 1023619169 NW 900 LOIS ST. NW **FINDS** N/A

< 1/8 0.105 mi. 557 ft.

Relative: Higher

**US BROWNFIELDS:** 

ATLANTA, GA 30318

**BELLWOOD QUARRY** Property Name:

Recipient Name: Atlanta, City of Actual: Grant Type: Assessment 934 ft.

Property Number: 5499014 or 17-0190-LL-028-6

Parcel size: 137 Latitude: 33.78160 -84.4358 Longitude: HCM Label: Not reported Map Scale: Not reported Point of Reference: Not reported Highlights: Not reported Datum: Not reported Acres Property ID: 83289 IC Data Access: Not reported Start Date: Not reported

Redev Completition Date: Not reported Completed Date: Not reported Acres Cleaned Up: Not reported Cleanup Funding: Not reported Not reported Cleanup Funding Source: Assessment Funding: Not reported Assessment Funding Source: Not reported Redevelopment Funding: Not reported Redev. Funding Source: Not reported Redev. Funding Entity Name: Not reported Redevelopment Start Date: Not reported Assessment Funding Entity: Not reported Cleanup Funding Entity: Not reported

Grant Type:

Accomplishment Type: Not reported

Accomplishment Count:

Cooperative Agreement Number: 98403696 Start Date: Not reported Not reported Ownership Entity: Completion Date: Not reported **Current Owner:** City of Atlanta Not reported Did Owner Change: Cleanup Required: Not reported Video Available: Not reported Photo Available: Not reported

Not reported Institutional Controls Required: IC Category Proprietary Controls: Not reported IC Cat. Info. Devices: Not reported IC Cat. Gov. Controls: Not reported IC Cat. Enforcement Permit Tools: Not reported IC in place date: Not reported IC in place: Not reported State/tribal program date: Not reported State/tribal program ID: Not reported State/tribal NFA date: Not reported Air contaminated: Not reported Air cleaned: Not reported Not reported Asbestos found:

Map ID Direction Distance

Elevation

MAP FINDINGS

Site EDR ID Number

EDR ID Number

EPA ID Number

Asbestos cleaned: Not reported Controled substance found: Not reported Not reported Controled substance cleaned: Drinking water affected: Not reported Drinking water cleaned: Not reported Groundwater affected: Not reported Groundwater cleaned: Not reported Not reported Lead contaminant found: Not reported Lead cleaned up: No media affected: Not reported Unknown media affected: Not reported Other cleaned up: Not reported Other metals found: Not reported Other metals cleaned: Not reported Other contaminants found: Not reported Other contams found description: Not reported Not reported PAHs found: PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported Petro products found: Not reported Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported Soil affected: Not reported Soil cleaned up: Not reported Surface water cleaned: Not reported VOCs found: Not reported Not reported VOCs cleaned: Cleanup other description: Not reported Num. of cleanup and re-dev. jobs: Not reported Past use greenspace acreage: Not reported Past use residential acreage: Not reported Surface Water: Not reported Past use commercial acreage: Not reported Not reported Past use industrial acreage: Not reported Future use greenspace acreage: Future use residential acreage: Not reported Future use commercial acreage: Not reported Future use industrial acreage: Not reported Greenspace acreage and type: Not reported Superfund Fed. landowner flag: Not reported Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Not reported Copper cleaned up: Iron cleaned up: Not reported mercury cleaned up: Not reported Nickel Cleaned Up: Not reported No clean up: Not reported Not reported Pesticides cleaned up: Selenium cleaned up: Not reported SVOCs cleaned up: Not reported Not reported Unknown clean up: Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported Not reported Chromium contaminant found: Copper contaminant found: Not reported Iron contaminant found: Not reported Map ID MAP FINDINGS

Distance Elevation

Site Database(s) EPA ID Number

Mercury contaminant found: Not reported Nickel contaminant found: Not reported No contaminant found: Not reported Pesticides contaminant found: Not reported Selenium contaminant found: Not reported SVOCs contaminant found: Not reported Unknown contaminant found: Not reported Not reported Future Use: Multistory Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Unknown media cleaned up: Not reported Past Use: Multistory Not reported

Property Description: currently active granite quarry

Below Poverty Number: Below Poverty Percent: 3.4 Meidan Income: 2614 Meidan Income Number: 102 Meidan Income Percent: 2.6 Vacant Housing Number: 19 Vacant Housing Percent: 13.8 Unemployed Number: 26 **Unemployed Percent:** 10.1

## FINDS:

Registry ID: 110060630296

Environmental Interest/Information System

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

<u>Click this hyperlink</u> while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

**EDR ID Number**